

PROJECT: Midnite Mine Remediation REPORT NO: 2021-13

OWNER: Newmont/Dawn Mining OPERATOR: Newmont/Dawn Mining

SUMMARY OF WORK ACTIVITIES OR EVENTS FOR THIS REPORTING PERIOD:

This weekly report provides a summary of Midnite Mine Site (Site) remediation action (RA) construction activities, quality assurance (CQA), quality control (CQC) and engineering activities for the period June 18 – 24, 2021. The Site activities discussed in this weekly report include, but are not limited to: Site Health, Safety, and Security; Community Liaison, Project Meetings, Regulatory Oversight, Site Visitors; Site Mobilization; RA Activities; Project Documentation; and Site Inspections.

The project SharePoint site includes the Project documentation discussed in this report. Access to the project SharePoint site is available at the following link: (b) (6)

SITE HEALTH, SAFETY, AND SECURITY

MIDNITE MINE HEALTH & SAFETY SUMMARY: Reporting Period June 18 – 24, 2021						
FIRST AID INJURY	0	PROPERTY DAMAGE	0			
MEDICALLY TREATED INJURY	0	NEAR MISS INCIDENT	0			
RESTRICTED WORK INJURY	0	RADIATION PROTECTION PLAN (RPP) – ISSUES	0			
		REPORTED				
LOST TIME INJURY	0					

Comments: there were no injuries or incidents this week. Helicopter delivery and installation of the rockfall attenuator system was successful and was executed to the plan.

COMMUNITY LIAISON

• Community notifications continue to be sent to Mr. Sherwood for site equipment deliveries and WTP Solids transport.

PROJECT MEETINGS, REGULATORY OVERSIGHT, AND SITE VISITORS

Weekly Progress Meeting:

The following stakeholders attended the Weekly Construction Progress meeting via a conference call on Wednesday, 23 June 2021 at 10:00;

- Jacobs
- Army Corps of Engineers (USACE)
- Dawn Mining Company (DMC)/Newmont
- WME
- AJAX
- Stantec

Meeting Action Items:

None

EPA Plan/Document Approvals:

 EPA approved the Pit 4 Overburden Upper Area Final Status Survey Work Plan on 24 June (with required revisions)



Regulatory Site Visit(s):

• Mark Fillius, USACE, was on Site on 18 June.

REMEDIAL WORK ACTIVITIES

Construction:

During the week of June 18 – 24, 2021, the following activities were conducted:

- Newmont excavated, hauled and placed low activity/low reactivity material from the west side of the South Waste Rock Pile (SWRP), the Pit 4 Overburden Pile, and the South Construction Support Zone (CSZ). Newmont placed these materials in the Pit 4 Waste Containment Area (WCA).
- · Newmont extended the west Infiltration Collectors
- SLV Earthmovers continued crushing and screening material from the Hillside Waste Rock Pile (HSWRP) to produce Drain Gravel, Liner Bedding and Geomembrane Bedding Material. Newmont hauled these materials to stockpile locations designated in the 2021 Crushing and Stockpiling Work Plan (Stantec, 2021). Estimated quantities of materials produced are presented in Table 1.
- Collection of Quality Control samples from the crushing and screening operation continued with samples
 of Drain Gravel, Liner Bedding, and Geomembrane Bedding Material submitted to Budinger and
 Associates for gradation analysis.
- Stantec performed Method 9 visible emissions observations at the crushing and screening operation on the HSWRP on 18 June. Visible dust from the crushing operation conformed with project requirements.
- Newmont continued monitoring water levels in the South Pond. Current data indicates the water level in the leak detection system increased.
- Hi-Tech Rockfall completed installing anchors for drapery mesh and attenuator systems on the west side of the Pit 3. Hi-Tech Rockfall and Northwest Helicopters installed the posts and wire mesh netting for the attenuator system on 21 and 24 Jun.
- Stantec performed South Pond Embankment Stability inspection on 25 June. The embankment remains stable, movement monitoring points remain within tolerance, and water level in the South Pond Piezometer is below pumping level. Ground water level in the South Pond piezometer was monitored daily and remains below action level.
- Newmont welded 10-inch HDPE pipe for the Pit 3 dewatering system. Newmont performed hydrostatic
 pressure test on the 3-inch HPDE GW-54 to South Pond pipeline. Results of the pressure test conformed
 with the project Specifications.
- Halme Construction continued to fuse HDPE pipe for the effluent pipeline.
- Halme Construction continued clearing and grubbing the effluent pipeline alignment along the New Access Road. Halme Construction completed clearing and grubbing between West End Road and Blue Creek Road where the pipeline alignment follows an overgrown jeep trail.

Table 1 – 2021 Production Estimates

Reporting Period			١	Annual				
Material	Planned Production (yd³)	Estimated Volume ¹ (yd³)	% of Planned	Planned Production (yd³)	Estimated Volume ¹ (yd³)	% of Planned	% Complete	
Haulage to Pit 4	Haulage to Pit 4							
SWRP	17,919	33,740	188%	315,523	433,832	137%	57%	
HSWRP	1,889	0	0%	23,246	2,828	12%	4%	



	Rep	orting Perio	d	Year-to-date			Annual	
Material	Planned Production (yd³)	Estimated Volume ¹ (yd ³)	% of Planned	Planned Production (yd³)	Estimated Volume ¹ (yd ³)	% of Planned	% Complete	
Pit 4 Overburden	14,700	36,736	250%	97,720	273,980	280%	82%	
South CSZ	0	5,348		0	14,308		286%	
Total	34,508	75,824	220%	436,489	724,948	166%	63%	
Aggregate Prod	luction							
Drain Gravel	8,500	8,314	98%	108,800	75,906	70%	25%	
Liner Bedding	0	250		8,610	6,807	79%	74%	
Geomembrane Bedding	8,500	8,200	96%	108,800	77,714	71%	20%	
Total	17,000	16,764	99%	226,210	160,427	71%	23%	

^{1 -} Truck load assumed to be 27 yd3

Stormwater Pollution Prevention Plan (SWPPP)

- Stantec performed the weekly SWPPP inspection on 24 June. No new BMPs or maintenance activities identified.
- Newmont continued installing diversion channel along the east edge of the Pit 4 Overburden Pile.
- Halme Construction installed BMPs along the effluent pipeline alignment between West End Road and Blue Creek Road and along Blue Creek Road.

Spill Prevention, Control, and Countermeasure Activities (SPCC)

Approximately 15 gallons of Transmission, Drive Train Oil (TDTO) spilled from the left, middle axle wheel
of a haul truck when the wheel seal failed. The truck was shut down as soon as the leak was observed
and absorbent pads were placed to absorb the leakage. Impacted soils were disposed of in Pit 4.

Equipment Mobilized/Demobilized and Material Delivered

The following equipment was mobilized to the Site during this reporting period.

- Halme Construction 2 bulldozers.
- Halme Construction horizontal directional drilling (HDD) equipment.

The following equipment was demobilized from the Site during this reporting period.

None.

All project owned non-road diesel equipment on Site is US-EPA Tier 4 compliant. On-site rental equipment and subsequent deliveries of rental equipment may be less than Tier 4 and will be assessed at the time of delivery.

Materials:

The following material was delivered to the Site during this reporting period.

None.



CONSTRUCTION QUALITY ASSURANCE

Dust Control and Monitoring

Seven dust monitors operated on site at the locations and for the time intervals listed in Table 2 below. There was no exceedance of the TSP action level (>260 μ g/m³) during this time-period.

Table 2 - TSP Dust Monitoring Locations during reporting period June 18 - 24, 2021

			Status						
Monitor ID	Location Description	Start Date	Fri	Sat	uns	Mon	anı	рәм	Thurs
ES-1 (stationary)	Midnite Mine Top of Pit 4	03/23/21	D/N			D/N	D/N	D/N	D/N
ES-2 (stationary)	Midnite Mine Southeast Boundary	03/23/21	D/N			D/N	D/N	D/N	D/N
ES-3 (stationary)	Midnite Mine West Boundary	03/23/21	D/N			D/N	D/N	D/N	D/N
ES-4 (roving)	Northeast Side of the SCSZ	04/16/21	D/N			D/N	D/N	D/N	D/N
ES-5 (roving)	Northeast of the Mid-SWRP	03/24/21	D/N			D/N	D/N	D/N	D/N
ES-6 (roving)	East of HSWRP above High Road	03/23/21	D/N			D/N	D/N	D/N	D/N
ES-7 (roving)	Northeast of HSWRP at Pit 4	03/23/21	D/N			D/N	D/N	D/N	D/N
ES-8 (stationary)	Northeast Rim of Pit 3	05/19/21	0			0	0	0	0

D=Day Shift (6:00 am to 4:30 pm)

N=Night Shift (4:00 pm to 2:30 am)

E=Environmental conditions (fog, smoke, pollen, heavy rain, etc.)

O=Off - Special Circumstances

Equipment malfunction (Battery/Power Supply or Other)

Project Documentation

Project CQA-CQC Field Acceptance Forms, Engineering Change Notices (ECNs), Design Clarification Notices (DCNs), Non-Compliance Notifications (NCNs), Requests for Information (RFIs), Submittals, and Other Items received during this time-period are shown in the table below:

CQA Documentation

CQC-CQA Fiel	d Acceptance Forms						
Acceptance No.	Title	CQC-CQA Issue Date					
None							
Project DCNs							
DCN No.	Title	Submittal Date	EPA Response Date				
None							
Project ECNs							
ECN No.	Title	Submittal Date	EPA Response Date				
2021-01	Monitoring and Control of Phreatic Levels in the South Pond Embankment	3/19/2021	Conditional Approval Received on 5/11/2021				
	Dewatering well pump test was conducted on Friday (5/28/2021).						
	EPA Comments – Provide a summary report of findings with a final plan for						



	dewatering. If dewatering is necessary, include a schedule for dewatering.			
2021-02	Modifications to Pit 3 Underdrain and Dewatering Sumps	6/8/2021	EPA - TBD	
Notice of Non-C				
NNC No. and Dates	Title/Description	CQA	CQA/EPA Response Date(s)	
NNC 2020-01 11/5/2020	South Pond Emergency Spillway Grout Grout Placement at Supplemental GCS	Close-out Pending Sign-offs	NNC 2020-01 Close- out Pending Completion of the	
	Completed on 5/12/2021. Provide 28-day Compressive Strength Grout		Supplemental GCS at GCS-04	
	Results - due on 6/9/2021. Received Passing Compressive Strength			
D	Results on 6/11/2021.			
Project RFIs	T		COA/EDA Desperso	
RFI No.	Title	CQC Submittal Date	CQA/EPA Response Date(s)	
HC-2021-04	Fiber Optic Cable Materials – Connectors Effluent Pipeline	5/26/2021	CQA – 6/18/2021 EPA Response Received 6/24/2021 –	
2001.01	Engineer's Input Received 6/17/2021	5/00/0004	No Concerns	
2021-04	Earthen Berm Pipe Anchor Stantec to Prepare Resubmittal Response	5/26/2021	CQA 6/4/2021 EPA – Disapproved 6/4/2021	
HC-2021-05	Use of Low-Pressure Air Test Instead of Hydrostatic Test Effluent Pipeline	6/7/2021	CQA – TBD EPA - TBD	
	Engineer's Response Received 6/17/2021			
Submittals	T-14	00001	004/504 0	
Submittal No.	Title	CQC Submittal Date	CQA/EPA Response Date(s)	
01300-04	Rockfall Mitigation Material Information for Pit 3	5/4/2021	CQA Acceptance 5/27/2021 EPA - TBD	
	Waiting on Manufacturer's Certification Letters from Geobrugg and Williams Form w/r/t MTRs			
02970-06.1	Revised - Midnite Mine Permanent Seed Mix List	6/7/2021	CQA – 6/15/2021 EPA – TBD	
	Due to lack of availability – substitute different varieties of the same species.			
HC-01575-02.1	Addendum to SPCC – Fuel Tanks Effluent Pipeline	6/10/2021	CQA – 6/14/2021 EPA - TBD	
	EPA returned with Comments – Discuss with EPA			
HC-02593-01.1	Engineered Manhole Drawings Effluent Pipeline	6/15/2021	CQA – TBD EPA - TBD	
	Stantec Requires: Stamped Structural Calculations, Manufacturer's Certs and Traffic-Rated Concrete Pad Design.			
HC-02200-01.1	Gradation Samples for Top/Base Course Effluent Pipeline	6/17/2021	CQA – 6/21/2021 EPA - TBD	



02970-07	Midnite Mine Temporary Erosion Seed Mix EPA Comment: Respond as to the plan for establishing the seed during the dry season.	6/22/2021	CQA – 6/23/2021 EPA Approval Received 6/24/2021				
02272-15	South Pond Geomembrane – 2021 Liner Repairs	6/21/2021	CQA – TBD EPA - TBD				
HC-02594-01.1	Calibration Certification for Halme Datalogger Effluent Pipeline	6/18/2021	CQA – 6/23/2021 EPA - TBD				
Other Items							
Item	Title	Comments					
None							

Copies of the updated CQA Logs are located on the project SharePoint site under the 2021 CQA Folder.

Site Inspections

Details regarding the four-phase CQA observation/inspection process for each definable work feature are summarized below and are further detailed in the daily CQC/CQA reports that are available on the project SharePoint site.

Preparatory Inspections / Meetings

None

Initial Phase Inspections

• Effluent Pipeline - Continued mobilized equipment inspections and clearing and grubbing limits

Follow-up Phase and Ongoing Inspections

- Effluent Pipeline HDPE pipe trial welds/welding
- South Pond Liner Leak investigation and repairs
- Hi-Tech Rockfall Scaling, installing additional wire mesh curtain panels, proof tests on attenuator post anchor bolts on west side of Pit 3.
- Checks on Mine Waste Placement in Pit 4 Low activity/low reactivity material from the SWRP, Middle Overburden Pile and South CSZ materials placed - no restrictions on placement.
- Periodic observations on placement of construction debris/trash in the Pit 4 WCA.
- Pit 3 Dewatering Pipe Welds for 10-inch DR11 HDPE Pipe
- Hydrostatic Test GW-54 3-inch DR11 HDPE Pipe

Completion Inspections

None

THREE WEEK LOOKAHEAD SCHEDULE

A copy of the Three Week Lookahead Schedule is provided as Attachment A.

Report completed and submitted by:

Andrew Liffring, P.E.

Project Construction Director

Attachments

• Attachment A – Midnite Mine 3 Week Lookahead Schedule

Photos of pertinent items are provided below.





Figure 1 – Excavating low activity/low reactivity material at the SWRP view looking North.




Figure 2 – Excavating low activity/low reactivity material at the Pit 4 Overburden, view looking Southeast.





Figure 3 – Drainage channel at the downslope limits of the Pit 4 Overburden Pile removal area.



Figure 4 – Placement low activity/low reactivity material in the Pit 4, view looking South.





Figure 5 – Installing GCL in Infiltration Collector in Pit 4.



Figure 6 – Crushing and screening operations at the HSWRP.





Figure 7 – Progress of visible Mine Waste removal from the CSZ.



Figure 8 – Conducting a preliminary gamma scan of the surface after removal of visible mine waste at the CSZ.





Figure 9 – Utility crew welding 10-inch DR11 HDPE for the Pit 3 dewatering pipeline



Figure 10 – Pit 3 rockfall protection attenuator posts installed



ATTACHMENT A

MIDNITE MINE THREE WEEK LOOKAHEAD SCHEDULE

